1. STATE Maryland COUNTY Cecil

VICINITY

STREET NO. Oakwood

ORIGINAL OWNER

ORIGINAL USE Dwelling

PRESENT OWNER

PRESENT USE Ruins WALL CONSTRUCTION Squared log grooved construction

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY CE - 36

DATE OR PERIOD Early 19th century? STYLE ARCHITECT

BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC

NO

This was a small log building two bays square and two stories in height which probably had an A-roof. (The roof is now completely gone.) This log dwelling was built into a slightly larger frames structure. The logs are square and laid in a grooved construction pattern, one on top of another. Many adze marks show on their surfaces. They are chinked between with plaster and fragments on broken brick.

This structure is important even in its ruinous state as one of the few surviving log structures in this county. site should be noted since it seems to be beyond repair. It is also interesting because it is two stories in height even though it is such a tiny structure.

Visited by MOB 4/70 - gone

Condition: RUINS

5. PHYSICAL CONDITION OF STRUCTURE

Endangered

Exterior

6. LOCATION MAP (Plan Optional) 3. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER

Paul Alan Brinkman 16 December 1967

12103

DATE OF RECORD

Form 10-445 (5/62)

OF SAME SIZE

SUPPLEMENTAL INFORMATION AND PHOTOCIAPHS MAY BE ADDED ON SHEET

1. STATE Haryland COUNTY Cecil TOWN Oakwood STREET NO.

VICINITY



ORIGINAL OWNER ---

ORIGINAL USE Dwelling PRESENT OWNER ----PRESENT USERULINS WALL CONSTRUCTION Squared construction NO. OF STORIES 2

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY CE-36

2. NAME

DATE OR PERIOD early 19th century? STYLE LOG ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC NO

This was a small log building two bayssquare and two stories in height which probably had an A-roof. (The roof is now completely gone.) This log dwelling was built into a slightly larger frame structure. The logs are square and laid in a grooved construction pattern, one on top of another. Many adze marks show on their surfaces. They are chinked between with plaster and fragments of broken brick.

This structure is important even in its ruinous state as ome of the few surviving log structures in this county. Its site should be noted since it seems to be beyond repair. It is also interesting because it is two stories in height even though it is such a tiny structure.

5. PHYSICAL CONDITION OF STRUCTURE

Interior

Exterior

6. LOCATION MAP (Plan Optional)

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

3 b= N 4=x 34"

7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER Paul Alan Brinkman 16 December 1967

DATE OF RECORD



CECIL CTY # 36 (G.36 39 DG 12/67



DAG/1967 NEG -MD. Hist. Trust





Ruined Log House Oakwood Cornering Detail

DAG/1967 NEG - MD. Hist. Trust